



STATE OF UTAH
NATURAL RESOURCES
Water Rights

Scott M. Matheson, Governor
Temple A. Reynolds, Executive Director
Dee C. Hansen, State Engineer

1636 West North Temple • Salt Lake City, UT 84116 • 801-533-6071

* M E M O R A N D U M *

TO: File
FROM: Richard B. Hall, P. E., Directing Engineer
SUBJECT: Field Review of the Upper San Pitch River Distribution System
DATE: September 24, 1984

A field review of the subject system was undertaken on September 18, 1984 with the following in attendance:

Perry Jensen
M. Stanley Adams

Kirk Forbush
Jerry L. Bronicel

Richard B. Hall

The following items were observed and/or discussed:

- 1) Rock Dam (Upper) - No measuring device in the canal; however, there are two stilling wells behind the gate, which could be calibrated.
- 2) Rock Dam (Lower) - No measuring device in the canal; the downstream gradient of the canal is very flat and a differential head scheme may be appropriate.
- 3) Bagnall Ditch - No measuring device.
- 4) West Point Ditch - No measuring device.
- 5) Moroni Canal - The Parshall Flume is located some 0.5 miles downstream of the point of diversion and is badly submerged due to sanding of a culvert below the flume.
- 6) Moroni Canal (City Ditch) - No measuring device.
- 7) Franson McArthur Ditch - Has a Parshall Flume with some submergence.
- 8) M & M Ditch (Not Observed) - Commissioner said diversion structure and measuring device were satisfactory.
- 9) Grady, Brady, & Mower Ditchers (Not observed) - Reported to have adequate diversions and measuring devices.
- 10) East Milburn Ditch - Rectangular Weir.
- 11) Meadow Ditch - Rectangular Weir.

12) West Milbourn Ditch (Not Observed) - The Parshall Flume needs to be reset.

The lower ditches on this system need measuring devices badly! However, we need to find out the gradients of the ditches to see if a Parshall Flume would work. If not, we should explore the "differential head" scheme of the diversion gates.

cc: Jerry L. Bronicel